

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Figure 1




Figure 2




Figure 3: Rotational
Cam Lock Assembly




Figure 4: Open Assembly




Figure 5: Locked Assembly.




Figure 6: Detail
View of Cam from
bottom.




Figure 7: Open Assembly with Rod in Place.

Figure 8: Cut Away View








Figure 10: Wedge Style without Rod






Figure 15: Wedge with Locking Tab. Note that the tab is cut from wedge in a way that provides a spring to allow the tab to deflect to slide into a slot in the body and spring back into the body slot to lock in position.

Third Variation:




Figure 16. Threaded Variant

Figure 16A. Threaded Variant




Figure 17. Threaded Variant -Locked Position




Fig 18




Fig 18




Fig 20




Fig 21